



## Contractors Equipment - Oxy Acetylene

Schematic



**1** = Cutting   **2** = Welding with Flexible Tip - Medium Pressure   **3** = Welding with Single Flame - Medium Pressure  
**4** = Multi-Flame Heating - Medium Pressure

## Contractors Equipment - Oxy Propane



**1** = Cutting   **2** = Brazing with Flexible Tip   **3** = Multi-Flame Heating   **4** = Single Flame Brazing